



## **Nebraska State Fire Marshal Pipeline Safety Section Investigation Report**

**SFM Deputy Conducting Inspection:**

**Arnie Bates**

**Call#:**

**8738**

**Report Date:**

**11/23/11**

**Inspection Type:**

**INCIDENT INVESTIGATION**

**Inspection Date(s):**

**11/22/2011**

**Operator Name:**

**Black Hills Energy**

**Unit:**

**Southern**

**Town/Site:**

**Geneva**

**Facility ID:**

**02-02-128**

*Narrative Summary*

Short summary of the Incident/Accident scenario

On September 30, 2011 Black Hills Energy (BHE) personnel installed a segment of 2" PE 2406 gas main from east side of 11<sup>th</sup> Street, west approximately 165' to an existing 2" steel mill-wrapped (mw) gas main. The 2" 2406 PE gas main was connected to what was thought to be a 6" PE 3408 15 psig main. The 2" steel mw gas main was stoppled, cut and capped by BHE contractor and north side of 2" mw main connected to new 2" PE 2406 gas main.

In reality, the new 2" 2406 PE main was connected to a 6" PE 3408 gas main operating at 52 psig (60 MAOP)

Existing 2" system serves approximately 31 customers operating at 15 psig system (which is the MAOP), is steel main with combination steel and PE services. The existing 2" steel mw main was connected to a tap on a 4" bare steel main, located near "old" TBS site.

**CONCLUSION**

- 1) Was natural gas and/or facilities involved? **YES**
- 2) Were there contributing factors? **Yes**
- 3) Violations of the Operator to Part 191 or Part 192? (Yes or No). **YES**
- 4) Recommendations to the operator to prevent reoccurrence.

**Findings:** Black Hills Energy personnel failed to verify pressures within existing segment of system before interconnecting to an existing elevated pressure main. This action introduced elevated pressure (52 psig) into an existing system with an MAOP of 15 psig. This action created a safety related condition that required prompt action on part of Black Hills Energy to remediate the issue.

**Violation:** 29 CFR Part 192. 619 Maximum allowable operating pressure - Steel or plastic pipelines:  
(a) No person may operate a segment of steel or plastic pipeline at a pressure that exceeds a maximum allowable operating pressure determined under paragraph (c) or (d) of this section, or the lowest of the following: (3) The highest actual operating pressure to which the segment was subjected during the 5 years preceding the applicable date in the second column. (July 1, 1965- July 1, 1970).

Region/State: Central / Nebraska

Reviewed by: \_\_\_\_\_

Principal Investigator: Arnie Bates

Title: \_\_\_\_\_

Date: November 22, 2011

Date: \_\_\_\_\_

**Pipeline System:** Geneva Distribution System      **Operator:** Black Hills Energy  
**Operator ID:** 15359      **Unit Number:** 02-02-000      **Activity Number:** 02-02-128  
**Location:** 1033 "O" Street      **Date of Occurrence:** Novemebr 22, 2011  
**Material Released:** NA      **Quantity:** NA  
**Arrival Time & Date:** 11:38 11/22/11      **Total Damages \$:** >\$5000  
**Investigation Responsibility:**     State     PHMSA     NTSB     Other

<i>Company Reported Apparent Cause:</i>		<i>Company Reported Sub-Cause (from PHMSA Form 7000-1/7100.2):</i>
<input type="checkbox"/>	Corrosion	
<input type="checkbox"/>	Natural Force Damage	
<input type="checkbox"/>	Excavation Damage	
<input type="checkbox"/>	Other Outside Force Damage	
<input type="checkbox"/>	Material Failure (Pipe, Joint, Weld)	
<input type="checkbox"/>	Equipment Failure	
<input checked="" type="checkbox"/>	Incorrect Operation	Failed to verify pressure in main before tie in
<input type="checkbox"/>	Other	

<i>Accident/Incident Resulted in (check all that apply):</i>		<i>Comments:</i>
<input type="checkbox"/>	Rupture	Over pressurization of main and services
<input type="checkbox"/>	Leak	
<input type="checkbox"/>	Fire	
<input type="checkbox"/>	Explosion	
<input type="checkbox"/>	Evacuation	Number of Persons: _____ Area: _____

<i>Failure Location &amp; Response</i>			
Location (City, Township, Range, County/Parish):		<b>NO Failure or incident (safety related condition)</b> (Acquire Map) Geneva NE NW corner of distribution system, work in area at intersection of 11 <sup>th</sup> Street & "O" Street.	
Address or M.P. on Pipeline: (1) 1033 "O" Street		Type of Area (Rural, City): (1) City, class II	
Coordinates of failure location (Latitude):		(Longitude):	
Date:		Time of Failure: No failure	
Time Detected: 11/21/11		Time Located:	
How Located: Verification of MAOP and Construction records			
NRC Report #: (Attach Report) NA		Time Reported to NRC: NA	Reported by: NA
<b>Type of Pipeline:</b>			
<input type="checkbox"/> Gas Distribution	<input type="checkbox"/> Gas Transmission	<input type="checkbox"/> Hazardous Liquid	<input type="checkbox"/> LNG
<input type="checkbox"/> LP	<input type="checkbox"/> Interstate Gas	<input type="checkbox"/> Interstate Liquid	
<input type="checkbox"/> Municipal	<input type="checkbox"/> Intrastate Gas	<input type="checkbox"/> Intrastate Liquid	
<input checked="" type="checkbox"/> Public Utility	<input type="checkbox"/> Gas Gathering	<input type="checkbox"/> Offshore Liquid	

<b>Failure Location &amp; Response</b>		
<input type="checkbox"/> Master Meter	<input type="checkbox"/> Offshore Gas	<input type="checkbox"/> Liquid Gathering
	<input type="checkbox"/> Offshore Gas - High H <sub>2</sub> S	<input type="checkbox"/> CO <sub>2</sub>
		<input type="checkbox"/> Low Stress Liquid
		<input type="checkbox"/> HVL
Pipeline Configuration (Regulator Station, Pump Station, Pipeline, etc.): Geneva Distribution system consisting of 60 psi MAOP and 15 psi MAOP sections. Pipe size ranging from 6" to 1/2" with pipe materials of bare steel, cathodically protected steel and polyethylene. This specific section is a 15 psi MAOP section, is a 5 block area consisting of 2300' of steel main with 31 services.		

<b>Operator/Owner Information</b>	
Owner: Black Hills Corporation Address: 1102 East 1 <sup>st</sup> Street Papillion NE 68046  Company Official: Phone No.:                      Fax No.:	Operator: Black Hills Energy Address: 510 North Commerce Street BEATRICE NE 68310  Company Official: Rick Schwartz Phone No. 402 332 3340      Fax No. 402 223 3397
<u>Drug and Alcohol Testing Program Contacts</u> <input type="checkbox"/> N/A	
Drug Program Contact & Phone:	
Alcohol Program Contact & Phone:	

<b>Damages</b>	
Product/Gas Loss or Spill <sup>(2)</sup> Amount Recovered Estimated Amount \$	Estimated Property Damage \$ Associated Damages <sup>(3)</sup> \$                      Repair only
Description of Property Damage: No property damage. Expense for repair and correction of system piping.	
Customers out of Service:	<input type="checkbox"/> Yes <input type="checkbox"/> No                      Number: na
Suppliers out of Service:	<input type="checkbox"/> Yes <input type="checkbox"/> No                      Number: na

<b>Fatalities and Injuries</b>					<input type="checkbox"/> N/A
Fatalities:	<input type="checkbox"/> Yes <input type="checkbox"/> No	Company:	Contractor:	Public:	
Injuries - Hospitalization:	<input type="checkbox"/> Yes <input type="checkbox"/> No	Company:	Contractor:	Public:	
Injuries - Non-Hospitalization:	<input type="checkbox"/> Yes <input type="checkbox"/> No	Company:	Contractor:	Public:	
Total Injuries (including Non-Hospitalization):		Company:	Contractor:	Public:	
Name	Job Function	Yrs. w/ Comp.	Yrs. Exp.	Type of Injury	

2 Initial volume lost or spilled  
 3 Including cleanup cost

<b>Fatalities and Injuries</b>					___ N/A

<b>Drug/Alcohol Testing</b>					___ N/A
Were all employees that could have contributed to the incident, post-accident tested within the 2 hour time frame for alcohol or the 32 hour time frame for all other drugs? ___ Yes    ___ No					
Job Function	Test Date & Time	Location	Results		Type of Drug
			Pos	Neg	

<b>System Description</b>	
Describe the Operator's System: Black Hills Energy, Geneva town distribution system has approximately 900 meters, 60 psi feeder main with and 15 psi MAOP pressure regulated district. TBS located at 11 <sup>th</sup> & R Street , DRS located at Alley north of "G" Street, west of 11th Street.	

<b>Pipe Failure Description</b>		___ N/A
Length of Failure (inches, feet, miles):		(1)
Position (Top, Bottom, include position on pipe, 6 O'clock):	Description of Failure (Corrosion Gouge, Seam Split):	(1)
Laboratory Analysis:            ___ Yes    ___ No		
Performed by:		
Preservation of Failed Section or Component:    ___ Yes    ___ No		
If Yes - Method:		
In Custody of:		
Develop a sketch of the area including distances from roads, houses, stress inducing factors, pipe configurations, direction of flow, etc. Bar Hole Test Survey Plot, if included, should be outlined with concentrations at test points.		

<b>Component Failure Description</b>		___ N/A
Component Failed:	(1)	
Manufacturer:	Model:	
Pressure Rating:	Size:	
Other (Breakout Tank, Underground Storage):		

<b>Pipe Data</b>		___ N/A
Material:	Wall Thickness/SDR:	
Diameter (O.D.):	Installation Date:	
SMYS:	Manufacturer:	

<i>Pipe Data</i>		___ N/A
Longitudinal Seam:	Type of Coating:	
Pipe Specifications (API 5L, ASTM A53, etc.):		

<i>Joining</i>		___
Type: welding	Procedure: API 1104	
NDT Method: visual	Inspected: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	

<i>Pressure @ Time of Failure @ Failure Site</i>					___ N/A
Pressure @ Failure Site:			Elevation @ Failure Site:		
Pressure Readings @ Various Locations:				Direction from Failure Site	
Location/M.P./Station #	Pressure (psig)	Elevation (ft msl)	Upstream	Downstream	

<i>Upstream Pump Station Data</i>		___ N/A
Type of Product:	API Gravity:	
Specific Gravity:	Flow Rate:	
Pressure @ Time of Failure <sup>(4)</sup>	Distance to Failure Site:	
High Pressure Set Point:	Low Pressure Set Point:	

<i>Upstream Compressor Station Data</i>		___ N/A
Specific Gravity:	Flow Rate:	
Pressure @ Time of Failure <sup>(4)</sup>	Distance to Failure Site:	
High Pressure Set Point:	Low Pressure Set Point:	

<i>Operating Pressure</i>		___
Max. Allowable Operating Pressure: 60 & 15 MAOP	Determination of MAOP: 60 MAOP by test, 15 MAOP by highest operating pressure in given time, 1965-1970	
Actual Operating Pressure: 52-57 & 15-12.5		
Method of Over Pressure Protection: District Regulating Station Relief device		
Relief Valve Set Point: 17 psig	Capacity Adequate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	

<i>Integrity Test After Failure</i>		___
Pressure test conducted in place? (Conducted on Failed Components or Associated Piping): <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
If No, tested after removal? <input type="checkbox"/> Yes <input type="checkbox"/> No		
Method: 15 psig pressure after removal of stopples. Replacement pipe was pretested @ 100 psi.		
Describe any failures during the test.		

<sup>4</sup> Obtain event logs and pressure recording charts

<b>Soil/water Conditions @ Failure Site</b>		___ N/A
Condition of and Type of Soil around Failure Site (Color, Wet, Dry, Frost Depth):		
Type of Backfill (Size and Description):		
Type of Water (Salt, Brackish):	Water Analysis <sup>(5)</sup> ___ Yes ___ No	

<b>External Pipe or Component Examination</b>		___
External Corrosion? ___ Yes ___x___ No <sup>(1)</sup>	Coating Condition (Disbonded, Non-existent): <sup>(1)</sup> Good condition	
Description of Corrosion: No issue		
Description of Failure Surface (Gouges, Arc Burns, Wrinkle Bends, Cracks, Stress Cracks, Chevrons, Fracture Mode, Point of Origin): Not applicable.		
Above Ground: ___ Yes ___x___ No <sup>(1)</sup>	Buried: ___x___ Yes ___ No <sup>(1)</sup>	
Stress Inducing Factors: NA <sup>(1)</sup>	Depth of Cover: 40" <sup>(1)</sup>	

<b>Cathodic Protection</b>		___
P/S (Surface): -1.032	P/S (Interface): -1.025	
Soil Resistivity: _____	pH: _____	Date of Installation: 1959
Method of Protection: Galvanic Anode		
Did the Operator have knowledge of Corrosion before the Incident? ___x___ Yes ___ No		
How Discovered? (Close Interval Survey, Instrumented Pig, Annual Survey, Rectifier Readings, ECDA, etc): Corrosion not an issue, No failure.		

<b>Internal Pipe or Component Examination</b>		___ N/A
Internal Corrosion: ___ Yes ___x___ No <sup>(1)</sup>	Injected Inhibitors: ___ Yes ___ No	
Type of Inhibitors:	Testing: ___ Yes ___ No	
Results (Coupon Test, Corrosion Resistance Probe):		
Description of Failure Surface (MIC, Pitting, Wall Thinning, Chevrons, Fracture Mode, Point of Origin):		
Cleaning Pig Program: ___ Yes ___ No	Gas and/or Liquid Analysis: ___ Yes ___ No	

<b>Internal Pipe or Component Examination</b>		___ N/A
Results of Gas and/or Liquid Analysis <sup>(6)</sup>		
Internal Inspection Survey: ___ Yes ___ No	Results <sup>(7)</sup>	
Did the Operator have knowledge of Corrosion before the Incident? ___ Yes ___ No		
How Discovered? (Instrumented Pig, Coupon Testing, ICDA, etc.):		

<b>Outside Force Damage</b>		___ N/A
Responsible Party:	Telephone No.:	
Address:		
Work Being Performed:		
Equipment Involved: <sup>(1)</sup>	Called One Call System? ___ Yes ___ No	
One Call Name:	One Call Report # <sup>(8)</sup>	
Notice Date:	Time:	
Response Date:	Time:	
Details of Response:		
Was Location Marked According to Procedures? ___ Yes ___ No		
Pipeline Marking Type: <sup>(1)</sup>	Location: <sup>(1)</sup>	
State Law Damage Prevention Program Followed? ___ Yes ___ No ___ No State Law		
Notice Required: ___ Yes ___ No	Response Required: ___ Yes ___ No	
Was Operator Member of State One Call? ___ Yes ___ No	Was Operator on Site? ___ Yes ___ No	
Did a deficiency in the Public Awareness Program contribute to the accident? ___ Yes ___ No		
Is OSHA Notification Required? ___ Yes ___ No		

<b>Natural Forces</b>		___ N/A
Description (Earthquake, Tornado, Flooding, Erosion):		

- 6 Attach copy of gas and/or liquid analysis report  
7 Attach copy of internal inspection survey report  
8 Attach copy of one-call report

<b>Failure Isolation</b>		__ N/A
Squeeze Off/Stopple Location and Method: <span style="float: right;">(1)</span> <b>Squeeze off on PE due west of interconnection. Stopple fitting on Steel each side of cut out.</b>		
Valve Closed - Upstream: Time:	I.D.: M.P.:	
Valve Closed - Downstream: Time:	I.D.: M.P.:	
Pipeline Shutdown Method: <input checked="" type="checkbox"/> Manual <input type="checkbox"/> Automatic <input type="checkbox"/> SCADA <input type="checkbox"/> Controller <input type="checkbox"/> ESD		
Failed Section Bypassed or Isolated:		
Performed By: BHE personnel	Valve Spacing:	

<b>Odorization</b>		__ N/A
Gas Odorized: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Concentration of Odorant (Post Incident at Failure Site):	
Method of Determination: <input type="checkbox"/> Yes <input type="checkbox"/> No	% LEL: <input type="checkbox"/> Yes <input type="checkbox"/> No	% Gas In Air: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
	Time Taken: <input type="checkbox"/> Yes <input type="checkbox"/> No	
Was Odorizer Working Prior to the Incident? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Type of Odorizer (Wick, By-Pass):	
Odorant Manufacturer: Model:	Type of Odorant:	
Amount Injected:	Monitoring Interval (Weekly):	
Odorization History (Leaks Complaints, Low Odorant Levels, Monitoring Locations, Distances from Failure Site):		

<b>Weather Conditions</b>		__ N/A
Temperature: cold/warming	Wind (Direction & Speed): NNW >5 mph	
Climate (Snow, Rain): clear	Humidity: 50%	
Was Incident preceded by a rapid weather change? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Weather Conditions Prior to Incident (Cloud Cover, Ceiling Heights, Snow, Rain, Fog):		

<b>Gas Migration Survey</b>		__
Bar Hole Test of Area: <input type="checkbox"/> Yes <input type="checkbox"/> No	Equipment Used: Flame Ionization	
Method of Survey (Foundations, Curbs, Manholes, Driveways, Mains, Services) <sup>(9)</sup> <span style="float: right;">(1)</span> FI survey of area (5 square blocks, 2300' main and 31 associated services. One UG leak reported (screwed fitting on riser) leak repaired by tightening.		

<b>Environment Sensitivity Impact</b>		__ N/A
Location (Nearest Rivers, Body of Water, Marshlands, Wildlife Refuge, City Water Supplies that could be or were affected by the medium loss): <span style="float: right;">(1)</span>		

<b>Environment Sensitivity Impact</b>		__ N/A
No issue		
OPA Contingency Plan Available? __ Yes __ No	Followed? __ Yes __ No	

<b>Class Location/High Consequence Area</b>		__
Class Location: 1 __ 2_x_ 3 __ 4 __ Determination:	HCA Area? __ Yes x__ No __ N/A Determination:	
Odorization Required? _x_ Yes __ No __ N/A		

<b>Pressure Test History</b>							__ N/A
<i>(Expand List as Necessary)</i>							
	Req'd <sup>(10)</sup> Assessment Deadline Date	Test Date	Test Medium	Pressure (psig)	Duration (hrs)	% SMYS	
Installation	2" mw	1959	Unk	Unk	Unk	unk	
Next MAOP Established	Operational MAOP			15	15	15 MAOP	
Next							
Most Recent	2" PE	9/30/11	Air	120	1	>20	
Describe any problems experienced during the pressure tests.							

<b>Internal Line Inspection/Other Assessment History</b>						__ N/A
<i>(Expand List as Necessary)</i>						
	Req'd <sup>(10)</sup> Assessment Deadline Date	Assessment Date	Type of ILI Tool <sup>(11)</sup>	Other Assessment Method <sup>(12)</sup>	Indicated Anomaly If yes, describe below	
Initial					__ Yes __ No	
Next					__ Yes __ No	
Next					__ Yes __ No	
Most Recent					__ Yes __ No	
Describe any previously indicated anomalies at the failed pipe, and any subsequent pipe inspections (anomaly digs) and remedial actions.						

<b>Pre-Failure Conditions and Actions</b>		__ N/A
Was there a known pre-failure condition requiring <sup>(10)</sup> the operator to schedule evaluation and remediation? __ Yes (describe below or on attachment) __ No		
If there was such a known pre-failure condition, had the operator established and adhered to a required <sup>(10)</sup> evaluation and remediation schedule? Describe below or on attachment. __ Yes __ No __ N/A		

10 As required of Pipeline Integrity Management regulations in 49CFR Parts 192 and 195  
 11 MFL, TFI, UT, Combination, Geometry, etc.  
 12 ECDA, ICDA, SCCDA, "other technology," etc.

<i>Pre-Failure Conditions and Actions</i>	___ N/A
Prior to the failure, had the operator performed the required <sup>(10)</sup> actions to address the threats that are now known to be related to the cause of this failure?    ___ Yes    ___ No    ___ N/A	
List below or on an attachment such operator-identified threats, and operator actions taken prior to the accident.	
Describe any previously indicated anomalies at the failed pipe, and any subsequent pipe inspections (anomaly digs) and remedial actions.	

<i>Maps &amp; Records</i>	___ N/A
Are Maps and Records Current? <sup>(13)</sup> ___x___ Yes    ___ No	
Comments:	

<i>Leak Survey History</i>	___ N/A
Leak Survey History (Trend Analysis, Leak Plots):	
Leakage survey conducted 11/22/11. FI walking Previous leakage survey of area 7/30-8/11/09 with 0 leak reported.	

<i>Pipeline Operation History</i>	___ N/A
Description (Repair or Leak Reports, Exposed Pipe Reports):	
Distribution system has been operating at 15 psig for past 30 years	
Did a Safety Related Condition Exist Prior to Failure?    ___ Yes    ___x___ No    Reported?    ___ Yes    ___x___ No	
Unaccounted For Gas: NA	
Over & Short/Line Balance (24 hr., Weekly, Monthly/Trend): NA	

<i>Operator/Contractor Error</i>		___ N/A
Name: Black Hills Energy personnel	Job Function: Ongoing investigation by BHE	
Title:	Years of Experience:	
Training (Type of Training, Background):		
Was the person "Operator Qualified" as applicable to a precursor abnormal operating condition?    ___Yes    ___ No    ___ N/A		
Was qualified individual suspended from performing covered task    ___ Yes    ___ No    ___x___ N/A		
Type of Error (Inadvertent Operation of a Valve): Failure to verify operational pressures of two different mains. Which led to the over pressurization of a segment of piping.		
Procedures that are required: Design/build review. Verification of pressures (hot tap) requirements.		
Actions that were taken: Prompt repair of piping when condition found.		
Pre-Job Meeting (Construction, Maintenance, Blow Down, Purging, Isolation): yes, pre tie-in.		

13 Obtain copies of maps and records

**Operator/Contractor Error**

\_\_\_ N/A

Prevention of Accidental Ignition (Tag & Lock Out, Hot Weld Permit): yes

Procedures conducted for Accidental Ignition: Isolation of gas flow, grounding,

Was a Company Inspector on the Job?  Yes  No

Was an Inspection conducted on this portion of the job?  Yes  No

Additional Actions (Contributing factors may include number of hours at work prior to failure or time of day work being conducted): **It is suspected that decision to install and connect to specific pipeline did not include engineering.** AND did not include verification of operational pressures.

Training Procedures:

Operation Procedures: failed to verify operational pressures before connecting pipelines

Controller Activities: NA

Name	Title	Years Experience	Hours on Duty Prior to Failure	Shift

Alarm Parameters:

High/Low Pressure Shutdown:

Flow Rate:

Procedures for Clearing Alarms:

Type of Alarm:

Company Response Procedures for Abnormal Operations:

Over/Short Line Balance Procedures:

Frequency of Over/Short Line Balance:

Additional Actions: Randy Wymore and Chad Hoffman (BHE personnel), completed a leakage survey of this segment of system. Wymore indicated that they had discovered several above grade leaks all class 3, and one underground leak on a riser (class 2), (leak was on a screwed coupling used to extend riser). Underground leak was repaired by tightening.

At approximately 12:55 BHE welder Dean Blazer arrived to complete tie in for 2" steel main. Preconstruction meeting for tie-in activity. At approximately 14:00 hours the existing caps were cut from 2" mw steel main. Visual inspection of these two welds indicated poor penetration of weld. Mick Porter will follow-up on the contract welder. (At this time the welder is believed to be Roger Carl). Was informed by Mick Porter at approximately 1430 hours that decision was made to pull welder certification and have him "re-qualify)

New pipeline segment added, approximately 24' of 2" A53 Grade B scd 40 black steel 24,000, pretested to 100 psig. Welded in place, visually inspected, purged to lower pressure to 15 psi, steel pipeline coated, anode attached. PE main cut and capped.

**Additional Actions Taken by the Operator**

\_\_\_N/A

Make notes regarding the emergency and Failure Investigation Procedures (Pressure reduction, Reinforced Squeeze Off, Clean Up, Use of Evacuators, Line Purging, closing Additional Valves, Double Block and Bleed, Continue Operating downstream Pumps):

Pipeline exposed and reconnected to proper feed. 15 psig system reinstated. 60 MAOP line capped.

During the month of September Kinder Morgan Interstate Gas Transmission Company (KMIGT) constructed at new Town Border Station (TBS) for Geneva NE.

In preparation of relocating existing facilities to new location, Black Hills Energy (BHE) personnel conducted construction activities to tie old system over to new town feeder.

On September 30, 2011 BHE personnel installed a segment of 2" PE 2406 gas main from east side of 11<sup>th</sup> Street, west approximately 165' to an existing 2" steel mill-wrapped (mw) gas main. The 2" 2406 PE gas main was connected to what was thought to be a 6" PE 3408 15 psig steel mw main. The 2" steel mw gas main was stoppled, cut and capped by BHE contractor, north side of 2" mw main connected to new 2" PE 2406 gas main.

In reality, the new 2" 2406 PE main was connected to a 6" PE 3408 gas main operating at 57 psig (60 MAOP)

Existing 2" system serves approximately 31 customers operating at 15 psig (which is the MAOP) System is steel main with combination steel and PE services. The existing 2" steel mw main was connected to a tap on a 4" bare steel main, located near "old" TBS.

In preparation of removing the old TBS, on 10/19/11 BHE personnel (Dean Blazer) stoppled, cut and capped a 4"mw steel main near old TBS. (this line was thought to be the main the 2" mw steel main was connected too!)

On November 18 BHE was contacted by KMIGT, indicating that there was still a "live" 4" bare steel gas main at the "old" TBS sight that needed to be terminated.

On November 21 after review of maps and records it was discovered and verified that an over pressurization had occurred. (15 psi MAOP system connected to a 60 psi MAOP main) and there was still a live 4" bare steel main at old TBS site.

This deputy contacted by phone on 11/22/11 by BHE indicating that an over pressurization had occurred and crews were being dispatched to correct the issue.

This deputy travel to Geneva to view construction activities, Met with Mick Porter and received maps of area. This area involved a section of Geneva bound on the east by 11<sup>th</sup> Street, on South by "O" Street, on west by 9<sup>th</sup> Street and north side being "Q" Street. System includes 31 services and meter sets.

At approximately 12:10 met with Randy Wymore and Chad Hoffman, who had completed a leakage survey of the system.

Randy indicated that they had discovered several above grade leaks and one underground leak on a riser (leak was on a screwed coupling used to extend riser). Underground leak had been repaired by tightening.

At approximately 12:55 BHE welder Dean Blazer arrived to complete tie in for 2" steel main.

At approximately 14:00 hours the existing caps were cut from 2" mw steel main. Visual inspection of these two welds indicated poor penetration of weld. Mick Porter will follow-up on the contract welder. (At this time the welder is believed to be Roger Carl).

**Photo Documentation** <sup>(1)</sup> NA

Overall Area from best possible view. Pictures from the four points of the compass. Failed Component, Operator Action, Damages in Area, Address Markings, etc.

Photo No.	Description	Photo No.	Description
1		16	
2		17	
3		18	
4		19	
5		20	
6		21	
7		22	
8		23	
9		24	




<b>Event Log</b>	
Sequence of events prior, during, and after the incident by time. (Consider the events of all parties involved in the incident, Fire Department and Police reports, Operator Logs and other government agencies.)	
Time / Date	Event
09/30/11	2" PE main extended to 2" steel 15 psi system, and connected to a 60 MAOP PE main.
11/21/11	First indicator that segment of system may be over pressurized. Confirmed MAOP and locations.
11/22/11	Crew dispatched. Repairs made to reinstate 15 psig MAOP operation.

<b>Failure Investigation Documentation Log</b>				
Operator:		Unit #:	CPF #:	Date:
Appendix	Documentation Description	Date	FOIA	
Number		Received	Yes	No
36-7N3W	BHE map Northwest Geneva (area effected)	11/22/11		X
36-7N3W [2]	BHE map Northwest Geneva As built new 2" PE	11/22/11		X
36-7N3W [3]	BHE map Northwest Geneva Original 2" install	11/22/11		X
36-7N3W [4]	BHE map Northwest Geneva Abandonment as built	11/22/11		X

<b>Site Description</b>
Provide a sketch of the area including distances from roads, houses, stress inducing factors, pipe configurations, etc. Bar Hole Test Survey Plot should be outlined with concentrations at test points. Photos should be taken from all angles with each photo documented. Additional areas may be needed in any area of this guideline.

Total 2298 2" MW



CALL BEFORE YOU DIG  
IN NE (800) 331-5666

Additional Notes



WR Information	Job Title
	Description

State	NE
County	FILLMORE
City	GENEVA

Scale	1"=161'
Twn/Rng/Sec	36-7N3W
WR Number	

Drawn By	MiPorter
Date Prepared	11/22/2011

WR1222  
6109-6" HDPE  
8/08/00

**ENGINEERING PAD**

Project Name TIED 2" MW to 6" MOPE  
for Switching over to NGW TBS


Page II Of III

W.O./File # 471364

Date 9-30-11

By SCHUSTER

②



FEET	SIZE	KIND	LOCATION
1064'	6"	M.W.	New location in North Geneva


CENTRAL ELECTRIC & GAS  
 TOWN, Geneva  
 J.O. - W.O. 2707 Int. No.     
 Date Started 8-10-29 Date Finished 8-11  
 Construction and Completion Report

FORM 6

T.B.S.  
 Geneva

4" Main

3






# ENGINEERING PAD

Project Name Cut off OLD TBS

Page III Of III  
W.O./File # 471364  
Date 10-19-11  
By SCHUSTER

①



During the month of September of 2011 Kinder Morgan Interstate Gas Transmission Company (KMIGT) constructed at new Town Border Station (TBS) for Geneva NE.

In preparation of relocating existing facilities to new location, Black Hills Energy (BHE) personnel conducted construction activities to tie existing system over to town feeder.

On September 30, 2011 BHE personnel installed a segment of 2" PE 2406 gas main from east side of 11<sup>th</sup> Street, west approximately 165' to an existing 2" steel mill-wrapped (mw) gas main. The 2" 2406 PE gas main was connected to what was thought to be a 6" PE 3408 15 psig steel mw main. The 2" steel mw gas main was stopped, cut and capped by BHE contractor, north side of 2" mw main connected to new 2" PE 2406 gas main.

In reality, the new 2" 2406 PE main was connected to a 6" PE 3408 gas main operating at 57 psig (60 MAOP)

Existing 2" segment of system serves approximately 31 customers operating at 15 psig (which is the MAOP) System is steel main with combination steel and PE services. The existing 2" steel mw main was connected to a tap on a 4" bare steel main, located near "old" TBS.

In preparation of removing the old TBS, on 10/19/11 BHE personnel (Dean Blazer) stopped, cut and capped a 4"mw steel main near old TBS. (this line was thought to be the main the 2" mw steel main was connected too!). The existing 2" mw steel main was connected to a 4" bare steel main, located just feet from the 4" mw steel main.

On November 18 BHE was contacted by KMIGT, indicating that there was still a "live" 4" bare steel gas main at the "old" TBS sight that needed to be terminated.

On November 21 after review of maps and records it was discovered and verified that an over pressurization had occurred. (15 psi MAOP system connected to a 60 psi MAOP main) and there was still a live 4" bare steel main at old TBS site.

This deputy was contacted by phone on 11/22/11 by BHE indicating that an over pressurization had occurred and crews were being dispatched to correct the issue.

This deputy travel to Geneva to view construction activities, Met with Mick Porter and received maps of area. This area involved a section of Geneva bound on the east by 11<sup>th</sup> Street, on South by "O" Street, on west by 9<sup>th</sup> Street and north side being "Q" Street. System includes 31 services and meter sets.

At approximately 12:10 met with Randy Wymore and Chad Hoffman, who had completed a leakage survey of the system. Randy indicated that they had discovered several above grade leaks and one underground leak on a riser (leak was on a screwed coupling used to extend riser). Underground leak had been repaired by tightening.

At approximately 12:55 BHE welder Dean Blazer arrived to complete tie in for 2" steel main.

At approximately 14:00 hours the existing caps were cut from 2" mw steel main. Visual inspection of these two welds indicated poor penetration of weld. Mick Porter will follow-up on the contract welder. (At this time the welder is believed to be Roger Carl). Was informed by Mick Porter at approximately 1430 hours that a decision was made to pull welder certification and have him "re-qualify".

New pipeline segment added, approximately 24"of 2" A53 Grade B schd 40 black steel 24,000 SMYS pretested to 100 psig. Welded in place, visually inspected, purged to lower pressure to 15 psi, anode attached, steel pipeline coated,. 2" 2406 PE main cut and capped.

Departed 16:15



## **Nebraska State Fire Marshal Pipeline Safety Section Investigation Supplemental**

**SFM Deputy Conducting Inspection:**

**Arnie Bates**

**Call#:**

**8738**

**Report Date:**

**01/20/2012**

**Inspection Type:**

**INCIDENT INVESTIGATION SUPPLEMENTAL**

**Inspection Date(s):**

**01/20/2012**

**Operator Name:**

**Black Hills Energy**

**Unit:**

**Southern**

**Town/Site:**

**Geneva**

**Facility ID:**

**02-02-128**

**NEBRASKA STATE FIRE MARSHAL'S OFFICE  
SUPPLEMENTAL REPORT**

<b>Name of Operator:</b>	Black Hills Energy Unit # Southern Town ID Geneva 02-02-128
<b>Operator Address:</b>	
Black Hills Energy 510 Commerce Street Beatrice NE 68	<b>Phone Number:</b> 402 332 3340 <b>Fax Number:</b> 402 233 3397 Emergency: 1-800-694-8989 Federal ID: 15359
<b>Person conducting Inspection</b> <b>Arnie Bates DSFM 8738</b>	 <b>Date:</b> January 20, 2012

**DATE OF INCIDENT:** 11/22/11  
**LOCATION:** 1033 "O" Street, Geneva NE

**DESCRIPTION:** On September 30, 2011 Black Hills Energy (BHE) personnel installed a segment of 2" PE 2406 gas main from east side of 11th Street, west approximately 165' to an existing 2" steel mill-wrapped (mw) gas main. The 2" 2406 PE gas main was connected to what was thought to be a 6" PE 3408 15 psig main. The 2" steel mw gas main was stoppled, cut and capped by BHE contractor and north side of 2" mw main connected to new 2" PE 2406 gas main.

In reality, the new 2" 2406 PE main was connected to a 6" PE 3408 gas main operating at 52 psig (60 MAOP)

Existing 2" system serves approximately 31 customers operating at 15 psig system (which is the MAOP), is steel main with combination steel and PE services. The existing 2" steel mw main was connected to a tap on a 4" bare steel main, located near "old" TBS site.

**PERSONS MENTIONED IN THIS REPORT**

Nathan Stewart, State Compliance Specialist, Black Hills Energy, Lincoln  
Clark Conklin, Chief Fuels Division, State Fire Marshal- Pipeline Safety Section, Lincoln

**BODY OF REPORT**

On or about January 18, 2012 this deputy received an electronic copy of a reply from STEWART, Black Hills Energy NOPV dated January 13, 2012. This was a reply to a Notice of Violation dated November 28, 2011. (20111128-N) that requested a response for corresponding determination of cause for the actions that led to the over pressurization of the Geneva gas system within 30 days. Latter an extension of time for reply was granted, extending the date to January 15, 2012.

The response letter stated:

Black Hills has conducted an investigation into the events that led to an over pressurization of a residential section of the Geneva distribution system. During the course of this investigation three items were uncovered as being key factors that led to the over-pressure situation:

- 1) Inadequate pre-job planning
- 2) Gauges not being used during tie-in
- 3) Warning signs missed

Had any of these three items been handled differently than they were, it is likely that the event would not have occurred or would have been discovered much earlier. Each of these items will be discussed in turn.

## Background

The overpressure occurred during the process of abandoning the town border station (owned by Kinder Morgan) and relocating it to the north side of Geneva on September 30, 2011. (See attachments I & 2) As a result of this project, several sections of main had to be abandoned inside the old town border station location. One of the sections of main being abandoned was a 2" mill wrapped main which ran northwest from the yard and served a residential section serving 31 customers. It was during the process of abandoning this line and installing a new one that the over-pressure occurred. (See attachment 3) This over pressure was discovered on November 21st during a review of records by area employees prompted by a call from Kinder Morgan regarding still "live" 4" main inside the old TBS location.

## Inadequate pre-job planning

During the course of the investigation it was discovered that mapping and pressure databases were not consulted to verify either the operating pressures or MAOP of the Geneva system. Instead, long term employees and their knowledge of the system were relied upon exclusively. In this particular instance, it was assumed based on field employees knowledge of the system that the 2" mill wrapped line feeding the residential section had always been connected to a 57lb high pressure gas main running through town. In reality, the line had always been tied to a 15lb "low pressure" gas main which was also in the town border station's yard. As a result of this belief, a new 2" PE line was connected to the 57lb line north of the old town border station and run west to feed the residential neighborhood. This action resulted in the over-pressure.

## Gauges

While tying the new 2" PE main to the 57lb mill wrapped main, no gauges were used to verify pressures on both sides of the tie-in. This procedure is outlined in Black Hills O&M 61.22. This procedure was not followed and the over-pressure occurred as a result. Had the procedure been followed, the difference in pressure between the two systems being tied together would have been discovered and over pressure would not have occurred.

## Warning signs

The process for installing the new feed to the residential section was to first install the new 2" feed and then abandon the existing 2" feed. Approximately 30 minutes elapsed between the time the connection of the new feed was made and when the old feed was cut and capped. For these 30 minutes until the abandonment was completed, the Geneva system was over-pressured from the residential section to the district regulator station in Geneva. This caused the regulator station to function properly and relieve the excess pressure from the piping.

This fact was noted by nearby bank employees who contacted Black Hills at I:15pm (September 30) about a smell of gas in the area. A service technician was dispatched at I:19pm to investigate. The technician arrived on site at 2:05pm and began his investigation. However, by the time he arrived at 2:05pm the station was no longer relieving pressure due to the fact that the abandonment of the 2" mill wrapped line had been completed by that time and pressure had gone back to its normal operating range. Responding service technician contacted operations personnel performing work in Geneva and informed them of the situation. Operations personnel investigated situation by verifying that the station was in fact no longer relieving pressure and by checking the pressure chart on the station. Not noting any significant anomalies on the chart, they concluded that the situation was not dangerous and did not investigate further.

Had this situation been investigated further, the over-pressure situation would have been discovered within a few hours and could have been corrected.

#### Preventative measures

Black Hills will take the following actions to prevent such an occurrence from happening in the future:

1) O&M sections regarding proper construction practices will be covered with all coordinators and operations employees during upcoming fusion certification training in February and March. Special attention will be given to the use of gauges during tie ins and proper use of mapping databases during the job planning process.

Additionally, the Geneva incident will be reviewed with all field employees during annual Emergency plan training conducted in February.

2) Educating field employees on proper use of gauges and following our existing standards regarding pressure monitoring while performing tie-ins.

3) Education will be held for all employees on proper investigation and follow up when district regulator stations are relieving pressure. This would involve contacting a supervisor who will then contact measurement department so that a full investigation of the event can be conducted.

**Initial Findings:** Black Hills Energy personnel failed to verify pressures within existing segment of system before interconnecting to an existing elevated pressure main. This action introduced elevated pressure (52 psig) into an existing system with an MAOP of 15 psig. This action created a safety related condition that required prompt action on part of Black Hills Energy to remediate the issue.

**Addition Findings:** 1)Black Hills Energy did conduct an investigation into the over-pressurization event in Geneva NE, with findings of Three key factors.

2) The actual investigation by Black Hills Energy had started prior to this deputy being notified of the event on November 22, or by a Notice letter of November 28, 2011, from State Fire Marshal - Pipeline Safety Section.

In review of BHE investigation, this deputy learned that over pressurization on gas mains and service was much larger in area than first indicated by this deputy. The area extend to a larger portion of the 15 psi system for up to 30 minutes on September 30, 2011. While the over-pressurization, of 31 services and associated main, investigated by this deputy continued for 53 days before being corrected.

The BHE report also indicated it was discovered that mapping and pressure databases were not consulted to verify either the operating pressures or MAOP of the Geneva system. Instead, long term employees and their knowledge of the system were relied upon exclusively.

The BHE report indicated that "no gauges were used to verify pressures on both sides of the tie-in. This procedure is outlined in Black Hills O&M 61.22."

The BHE report also concluded that "had initial indications of a problem been investigated further, the over-pressure situation would have been discovered within a few hours and could have been corrected. Initial indication was the operation of relief device at District Regulator Station.

The BHE letter proposed 3 preventive measures to be taken to prevent such an occurrence from happening in the future.

1) O&M sections regarding proper construction practices will be covered with all coordinators and operations employees during upcoming fusion certification training in February and March. Special attention will be given to the use of gauges during tie ins and proper use of mapping databases during the job planning process. Additionally, the Geneva incident will be reviewed with all field employees during annual Emergency plan training conducted in February.

2) Educating field employees on proper use of gauges and following our existing standards regarding pressure monitoring while performing tie-ins.

3) Education will be held for all employees on proper investigation and follow up when district regulator stations are relieving pressure. This would involve contacting a supervisor who will then contact measurement department so that a full investigation of the event can be conducted.

**Initial Violation:** 49 CFR Part 192. 619 Maximum allowable operating pressure - Steel or plastic pipelines: (a) No person may operate a segment of steel or plastic pipeline at a pressure that exceeds a maximum allowable operating pressure determined under paragraph (c) or (d) of this section, or the lowest of the following: (3) The highest actual operating pressure to which the segment was subjected during the 5 years preceding the applicable date in the second column. (July 1, 1965- July 1, 1970).

Additional violation as a result of investigation by Black Hills Energy.

Failure to follow Operation and Maintenance Procedures BHE O&M 61.22

§192.605 Procedural manual for operations, maintenance, and emergencies (a) General. Each operator shall prepare and follow for each pipeline, a manual of written procedures for conducting operations and maintenance activities and for emergency response.

Failed to design a system to prevent accidental over-pressurization.

§192.195 Protection against accidental overpressuring.

(b) Additional requirements for distribution systems. Each distribution system that is supplied from a source of gas that is at a higher pressure than the maximum allowable operating pressure for the system must

(2) Be designed so as to prevent accidental overpressuring.

**CONCLUSION:** The root cause of the event rests solely with Black Hills Energy, the failure to follow operating procedures caused the pressure within the mains and services to exceed the maximum allowable operating pressure designation. Black Hills Energy did not deny that their actions caused this to happen.

It appears that a lack of recognition of an abnormal operating condition and an incomplete reaction to that condition caused the condition to continue for 53 days. On the surface there may be an issue with qualification of personnel concerning the ability to recognize and react to an



**SFM Deputy Conducting Inspection:**

**Arnie Bates**

**Call#:**

**8738**

**Report Date:**

**Jan. 25, 2012**

**Inspection Type:**

**INCIDENT INVESTIGATION SUPPLEMENTAL**

**Inspection Date(s):**

**Jan. 23-24-25, 2012**

**Operator Name:**

**Black Hills Energy**

**Unit:**

**Southern**

**Town/Site:**

**Geneva**

**Facility ID:**

**02-02-128**

## SUPPLEMENTAL REPORT

<b>Name of Operator:</b>	Black Hills Energy <b>Unit #</b> Southern <b>Town ID</b> Geneva 02-02-128
<b>Operator Address:</b>	
Black Hills Energy 510 Commerce Street Beatrice NE 68	<b>Phone Number:</b> 402 332 3340 <b>Fax Number:</b> 402 233 3397 <b>Emergency:</b> 1-800-694-8989 <b>Federal ID:</b> 15359
<b>Person conducting Inspection</b> <b>Arnie Bates DSFM 8738</b>	 <b>Date:</b> January 23-24 & 25, 2012

**DATE OF INCIDENT:** 11/22/11

**LOCATION:** 1033 "O" Street, Geneva NE

**DESCRIPTION:** On going investigation into the over pressurization of the Geneva distribution system.  
Found Nov 21, 2011

January 23, 2012 This deputy met with Clark Conklin and Regina Shields to discuss events concerning the vents concerning the over-pressurization of the Geneva gas distribution system.

Initial NOPV (20111123-N) was issued to Black Hills Energy for failing to verify pressures within the natural gas distribution system and caused pressures within the piping to exceed the current Maximum Allowable Operating Pressure (MAOP) for a segment of natural gas main and services.

Part 192§619 Maximum allowable operating pressure - Steel or plastic pipelines: (a) No person may operate a segment of steel or plastic pipeline at a pressure that exceeds a maximum allowable operating pressure determined under paragraph (c) or (d) of this section, or the lowest of the following: (3) The highest actual operating pressure to which the segment was subjected during the 5 years preceding the applicable date in the second column. (July 1, 1965- July 1, 1970).

During subsequent investigation and as a result of review of the Black Hills Energy incident investigation (response from Black Hills Energy dated January 13, 2012 and received January 18, 2012). It was not contended that Black Hills Energy was not in violation of Title 155 Nebraska Administrative Code Chapter 1.001 adopting by reference Pipeline Safety Regulations Title 49, Code of Federal Regulations, Part 192§619(a)(3) above.

In addition this deputy has reason to believe that actions by Black Hills Energy personnel (BHE) did not follow basic Operations and Maintenance Procedures which could have prevented the over-pressurization from happening. **A violation of Part 192.605(a).**

§192.605 Procedural manual for operations, maintenance, and emergencies (a) General. Each operator shall prepare and follow for each pipeline, a manual of written procedures for conducting operations and maintenance activities and for emergency response.

Specifically, Black Hills Energy personnel failed to follow Operation and Maintenance Procedures when conducting a tie-in (starting up new segment of pipeline between two existing pipe systems). Black Hills Energy personnel did not follow the procedures required by 192.605(b)(5) which are stated in *Black Hills Energy Operation and Maintenance Manual 61.22*, that requires gauges to be installed to verify pressures in the piping system. Part 192.605(b)(5) requires that the Operation and Maintenance manual have procedures.

§192.605 Procedural manual for operations, maintenance, and emergencies (b) Maintenance and normal operations. The manual required by paragraph (a) of this section must include procedures for the following, if applicable, to provide safety during maintenance and operations. (5) Starting up and shutting down any part of the pipeline in a manner designed to assure operation within the MAOP limits prescribed by this part, plus the build-up allowed for operation of pressure-limiting and control devices.

Reference: *Black Hills Energy Operation and Maintenance Manual 61.22*

*BHE O&M section 61 General Construction Practices*

*61.22 STARTING UP AND SHUTTING DOWN A PIPELINE DURING NORMAL OPERATION*

*When a pipeline is put into service, it shall have pressure-limiting, and/or control devices, and gauges connected to the pipeline, so that the MAOP plus allowable buildup will not be exceeded.*

In addition this deputy believes that Black Hills Energy personnel failed to design a repair to the Geneva distribution system that would have prevented accidental over-pressurization. A part of this design process should have included multiple independent department checks to ensure the proposed alterations would not result in an over pressurization. **A violation of 192.195(b)(2)**

In this particular instance, Black Hills Energy assumed based on field employees knowledge of the system that the 2" mill wrapped line feeding the residential section had always been connected to a 57lb high pressure gas main running through town. In reality, the line had always been tied to a 15lb "low pressure" gas main which was also in the town border station's yard. Without visually inspecting maps, consultation of pressure data system, or verification of actions through Black Hills Energy "STORMS" system (a computer program that is utilized by Black Hills Energy to create mapping, a part of which can flow model existing pipeline systems) which can show the results of tying two pipelines together.

*Black Hills Energy Operation and Maintenance Manual 52.3.1 & 52.3.2*

## **Section 52 : Project Preparation**

### **52.1 SCOPE**

*This section presents Company standards dealing with the location of distribution, transmission and gathering systems and facilities, as well as pre-construction requirements and related planning efforts to aid in resolving potential problems that can be identified in advance of actual construction activity. Consideration of pre-construction requirements and related planning efforts will aid in resolving potential problems that can be identified in advance of actual construction activity.*

### **52.3 FACTORS TO CONSIDER PRIOR TO CONSTRUCTION**

*Consider the following factors prior to starting construction.*

#### **52.3.1 JOB DRAWINGS**

*As soon as the drawings and/or work order information is received, examine in detail the print of the proposed installation and all other specific information. The drawings and other specific information on the job must always be available to the inspector before the beginning of construction.*

#### **52.3.2 IDENTIFY THE GEOGRAPHICAL LAYOUT OF THE INSTALLATION**

- 1. What part of the system does this installation tie into?*
- 2. Will the project affect normal operation of the system?*
- 3. Are there likely to be any foot or vehicular traffic problems?*
- 4. Will this job create problems for commercial or civic establishments during construction?*

### **CONCLUSION**

- 1) Was natural gas and/or facilities involved? **YES**
- 2) Were there contributing factors? **Yes**
- 3) Violations of the Operator to Part 191 or Part 192? **YES**
- 4) Recommendations to the operator to prevent reoccurrence. **On going**

**Findings:** Black Hills Energy personnel failed to verify pressures within existing segment of system before interconnecting to an existing elevated pressure main. (original violation Part 192.619(a))

Black Hills Energy personnel failed to follow their own procedures when (a) starting up a system, a violation of Part192.605(a).

Black Hills Energy personnel failed to follow procedures in designing a repair (addition) to the Geneva distribution system, a violation of Part192.195(b)(2).

On a subsequent thoughts there maybe underlying issues with OQ.

(1) The process for installing the new feed to the residential section was to first install the new 2" feed and then abandon the existing 2" feed. Approximately 30 minutes elapsed between the time the

connection of the new feed was made and when the old feed was cut and capped. For these 30 minutes until the abandonment was completed, the Geneva system was over-pressured from the residential section to the district regulator station in Geneva. This caused the regulator station to function properly and relieve the excess pressure from the piping.

This fact was noted by nearby bank employees who contacted Black Hills at 1:15pm

(September 30) about a smell of gas in the area.

A service technician was dispatched at 1:19pm to investigate.

The technician arrived on site at 2:05pm and began his investigation. However, by the time he arrived at 2:05pm the station was no longer relieving pressure due to the fact that the abandonment of the 2" mill wrapped line had been completed by that time and pressure had gone back to its normal operating range. Responding service technician contacted operations personnel performing work in Geneva and informed them of the situation. Operations personnel investigated situation by verifying that the station was in fact no longer relieving pressure and by checking the pressure chart on the station. Not noting any significant anomalies on the chart, they concluded that the situation was not dangerous and did not investigate further.

Had this situation been investigated further, the over-pressure situation would have been discovered within a few hours and could have been corrected.

As a result of not following up a section of Geneva distribution system was exceeding the MAOP for 52 days.

Depending upon the location of the pressure taps, it is possible that the "Chart" never registered the over pressure event. The relief functioned (did its job) but how much of the system was over-pressurized? That is a guess at this time.

**END OF REPORT**

abnormal operating condition. Underlying may be a need to more thoroughly investigate WHY an event occurred.

While the event did not lead to an "incident" as defined by CFR 29 Part 191, the situation did put the public at a considerably higher risk. The resulting consequences of that heightened risk could have resulted in loss of life, injury to public, large loss of revenue because of resulting damages to both public and Company, and damage to reputation of personnel and Black Hills Energy as a Company.

With these issues presented, it is the belief of this deputy that actions should be pursued and information forwarded to the Attorney Generals Office.

- 1) Was natural gas and/or facilities involved? **YES**
- 2) Were there contributing factors? **Yes**
- 3) Violations of the Operator to Part 191 or Part 192? **YES**
- 4) Recommendations to the operator to prevent reoccurrence: **YES**

Application of Black Hills Energy investigation findings and suggested preventative measures;

- 1) O&M sections regarding proper construction practices will be covered with all coordinators and operations employees during upcoming fusion certification training in February and March. Special attention will be given to the use of gauges during tie-ins and proper use of mapping databases during the job planning process.

Additionally, the Geneva incident will be reviewed with all field employees during annual Emergency plan training conducted in February.


- 2) Educating field employees on proper use of gauges and following our existing standards regarding pressure monitoring while performing tie-ins.
- 3) Education will be held for all employees on proper investigation and follow up when district regulator stations are relieving pressure. This would involve contacting a supervisor who will then contact measurement department so that a full investigation of the event can be conducted.

**END OF REPORT**

Received on:

JAN 18 2012

NE State Fire Marshal



Arnie Bates  
Deputy Fire Marshal  
Nebraska State Fire Marshal  
Pipeline Safety Division  
246 South 14th Street  
Lincoln, NE 68508-1804

January 13, 2011

RE: 20111123--N

Dear Mr. Bates,

Enclosed you will find a response to a letter sent to our office on November 23, 2011 in regard to an overpressure of part of the Geneva system.

If you have questions regarding this response, please contact me at (402) 437-1734 or email at [nathan.stewart@blackhillscorp.com](mailto:nathan.stewart@blackhillscorp.com).

Sincerely,

A handwritten signature in black ink, appearing to read "Nathan Stewart".

Nathan Stewart  
State Compliance Specialist

Black Hills has conducted an investigation into the events that led to an over pressurization of a residential section of the Geneva distribution system. During the course of this investigation three items were uncovered as being key factors that led to the over-pressure situation:

- 1) Inadequate pre-job planning
- 2) Gauges not being used during tie-in
- 3) Warning signs missed

Had any of these three items been handled differently than they were, it is likely that the event would not have occurred or would have been discovered much earlier. Each of these items will be discussed in turn.

## **Background**

The overpressure occurred during the process of abandoning the town border station (owned by Kinder Morgan) and relocating it to the north side of Geneva on September 30, 2011. (*See attachments 1 & 2*) As a result of this project, several sections of main had to be abandoned inside the old town border station location. One of the sections of main being abandoned was a 2" mill wrapped main which ran northwest from the yard and served a residential section serving 31 customers. It was during the process of abandoning this line and installing a new one that the over-pressure occurred. (*See attachment 3*) This over pressure was discovered on November 21<sup>st</sup> during a review of records by area employees prompted by a call from Kinder Morgan regarding still "live" 4" main inside the old TBS location.

## **Inadequate pre-job planning**

During the course of the investigation it was discovered that mapping and pressure databases were not consulted to verify either the operating pressures or MAOP of the Geneva system. Instead, long term employees and their knowledge of the system were relied upon exclusively.

In this particular instance, it was assumed based on field employees knowledge of the system that the 2" mill wrapped line feeding the residential section had always been connected to a 57lb high pressure gas main running through town. In reality, the line had always been tied to a 15lb "low pressure" gas main which was also in the town border station's yard. As a result of this belief, a new 2" PE line was connected to the 57lb line north of the old town border station and run west to feed the residential neighborhood. This action resulted in the over-pressure.

## **Gauges**

While tying the new 2" PE main to the 57lb mill wrapped main, no gauges were used to verify pressures on both sides of the tie-in. This procedure is outlined in Black Hills O&M 61.22. This procedure was not followed and the over-pressure occurred as a result. Had the procedure been followed, the difference in pressure between the two systems being tied together would have been discovered and over pressure would not have occurred.

## **Warning signs**

The process for installing the new feed to the residential section was to first install the new 2" feed and then abandon the existing 2" feed. Approximately 30 minutes elapsed between the time the connection of the new feed was made and when the old feed was cut and capped. For these 30 minutes until the abandonment was completed, the Geneva system was over-pressured from the residential section to the district regulator station in Geneva. This caused the regulator station to function properly and relieve the excess pressure from the piping.

This fact was noted by nearby bank employees who contacted Black Hills at 1:15pm (September 30) about a smell of gas in the area. A service technician was dispatched at 1:19pm to investigate. The technician arrived on site at 2:05pm and began his investigation. However, by the time he arrived at 2:05pm the station was no longer relieving pressure due to the fact that the abandonment of the 2" mill wrapped line had been completed by that time and pressure had gone back to its normal operating range. Responding service technician contacted operations personnel performing work in Geneva and informed them of the situation. Operations personnel investigated situation by verifying that the station was in fact no longer relieving pressure and by checking the pressure chart on the station. Not noting any significant anomalies on the chart, they concluded that the situation was not dangerous and did not investigate further. Had this situation been investigated further, the over-pressure situation would have been discovered within a few hours and could have been corrected.

## **Preventative measures**

Black Hills will take the following actions to prevent such an occurrence from happening in the future:

- 1) O&M sections regarding proper construction practices will be covered with all coordinators and operations employees during upcoming fusion certification training in February and March. Special attention will be given to the use of gauges during tie ins and proper use of mapping databases during the job planning process.

Additionally, the Geneva incident will be reviewed with all field employees during annual Emergency plan training conducted in February.

- 2) Educating field employees on proper use of gauges and following our existing standards regarding pressure monitoring while performing tie-ins.
  
- 3) Education will be held for all employees on proper investigation and follow up when district regulator stations are relieving pressure. This would involve contacting a supervisor who will then contact measurement department so that a full investigation of the event can be conducted.





N

New TBS location

Over-pressured housing

Old TBS location

© 2011 Google


Image © 2012 DigitalGlobe

Google earth

Imagery Date: 4/5/2006 1993

40° 32' 19.79" N 97° 36' 12.55" W elev 1627 ft

Eye alt 3500 ft



New TBS location

New 2" PE main attached to 57lb main, raising the pressure of the neighborhood above it's MAOP.

2" mill wrapped line that previously served residential section. This line was attached to the 4" bare steel line operated at 15 lbs. This line was abandoned approximately 30 minutes after new 2" PE line was installed.

4" bare steel line operated at 15lbs. Residential section was previously connected to this line. Field assumed that this line had been abandoned for years and

4" mill wrapped line operated at 57lbs. Field mistakenly assumed that the 2" mill wrapped line was attached to this main.

# STATE OF NEBRASKA



## Letter of Approval

Dave Heineman  
Governor

STATE FIRE MARSHAL  
John Falgione  
Fire Marshal

September 14, 2012

Rick Schwartz  
Black Hills Energy  
510 North Commerce Street  
Beatrice, NE 68310

RE: Notice of Probable Violation – #20111128-N, Over pressurization of main and services in Geneva NE.

The State Fire Marshal Office, Fuels Division, Pipeline Safety has conducted follow-up investigation of actions that led to a safety related condition in a northwest section of the Geneva distribution system. As a result of this investigation the Pipeline Safety Section will close additional action on this violation of Title 155 Nebraska Administrative Code Chapter 1.001 adopting by reference Pipeline Safety Regulations Title 49, Code of Federal Regulations, Part 192, subsection 619 Maximum allowable operating pressure - Steel or plastic pipelines.

In closing this action, we have considered the following actions of Black Hills Energy in resolving this issue:

- The initial reporting of the condition of over pressurization.
- Internal investigation of actions of personnel that led to the event of over pressurization and the resulting clarification to personnel, on duties during design, construction and tie-in of pipeline segments.
- Revised training for Black Hills Energy personnel and contractors in the process of tapping and tie-in of pipeline segments including specific pressure checks.
- Implementation of redundant checks during design and construction of pipeline segments with possible different maximum allowable operating pressures (MAOP).
- Field inspections during construction activities to verify personnel are conducting pressure checks within the pipeline segment.

We appreciate your attention to this matter and steps taken to eliminate future reoccurrence of this nature. If you have any questions regarding the substance or propriety of this letter, please contact our office at, Nebraska State Fire Marshal, Pipeline Safety Section, 246 South 14<sup>th</sup> Street, Lincoln NE 68508-1804 or telephone 402 471 9664.

Arnie Bates,  
Deputy Fire Marshal  
Pipeline Safety Section  
308-390-0460

Clark Conklin,  
Chief Deputy Fire Marshal  
Fuels Safety Division  
402- 471-9465

cc: Nathan Stewart, P. O. Box 83008, Lincoln, NE 68501-3008  
Cullen Sila, P. O. Box 548, 720 South Lincoln Avenue, York, NE 68467-0548  
Mick Porter, 510 North Commerce Street, Beatrice, NE 68310

MAIN OFFICE

DISTRICT A  
246 South 14<sup>th</sup> Street  
Lincoln, NE 68508-1804  
(402) 471-2027

DISTRICT B

438 West Market  
Albion, NE 68620-1241  
(402) 395-2164

DISTRICT C

200 South Silber  
North Platte, NE 69101-4219  
(308) 535-8181

FUELS DIVISION

FLST  Pipeline  
246 South 14<sup>th</sup> Street  
Lincoln, NE 68508-1804  
(402) 471-9465

TRAINING DIVISION

2410 North Wheeler Avenue  
Suite 112  
Grand Island, NE 68801-2376  
(308) 385-6892