



State of Nebraska

Underground Storage Tank Summary Information

Report Period: October 1, 2016 to September 30, 2017

This report has been prepared pursuant to EPA's Public Record UST Grant Guidelines.

Questions about the General Information and On-Site Inspections may be addressed to the State Fire Marshal's Office at 402-471-9465. Questions about Confirmed Releases may be addressed to the Department of Environmental Quality Petroleum Remediation Section at 402-471-2186. For a list of "Leaking UST and Surface Spill Sites" see NDEQ's website at www.deq.state.ne.us under Programs/Petroleum Remediation/LUST & Surface Spill Site Information.

Date Posted: 10/26/2017

General Information

Total Number of UST Facilities: 2,307
 Total Number of USTs: 6,525

On Site Inspections

UST Facilities Inspected: **1,043**

Percentage of Facilities Inspected Found To Be In Compliance **61%**
(With Release Detection and Release Prevention Regulations)

Releases

of Confirmed UST Releases: 69

Leak Autopsy Report

| Source | | | Cause | | | | | | | | | | | | | |
|--------------------------|----|------|-------|------|----------|------|------------------|------|-----------|------|-----------------|------|-------|------|---------|------|
| | | | Spill | | Overfill | | Phys/Mech Damage | | Corrosion | | Install Problem | | Other | | Unknown | |
| # | % | # | % | # | % | # | % | # | % | # | % | # | % | # | % | |
| Tank | 19 | 28% | 0 | 0% | 11 | 52% | 0 | 0% | 4 | 100% | 0 | 0% | 0 | 0 | 4 | 13% |
| Piping | 9 | 13% | 0 | 0% | 0 | 0% | 6 | 55% | 0 | 0% | 0 | 0 | 0 | 0 | 3 | 09% |
| Dispenser | 15 | 22% | 1 | 100% | 10 | 48% | 4 | 36% | 0 | 0% | 0 | 0% | 0 | 0 | 0 | 0% |
| Submersible Turbine Pump | 1 | 1% | 0 | 0% | 0 | 0% | 1 | 9% | 0 | 0% | 0 | 0% | 0 | 0 | 0 | 0 |
| Other (e.g. unknown) | 25 | 36% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0 | 25 | 78% |
| Totals | 69 | 100% | 1 | 100% | 22 | 100% | 11 | 100% | 4 | 100% | 0 | 100% | 0 | 100% | 32 | 100% |