### Nebraska State Fire Marshal Fuels Safety Division—FLST Section





Facility Name: STINGERS ONE STOP

Facility ID #: 2377

Date of Inspection: 05/01/2025

Jurisdiction: NE

Inspection Type	Action		
Initial	Orders Issued		
Revisit	Tanks Approved (List SFM ID#s):		
	Operating Permit To Follow		
	<b>GIS:</b> N42*35.921' W097*38.641' ELEV. 1725		
	Delivery Prohibited (List SFM ID#s): 07 & 08		



Good Life. Great Safety.

STATE FIRE MARSHAL AGENCY



Jim Pillen, Governor

May 1, 2025

Bash Investors LLC Atten: Jeremy Gill 202 E Main, St Bloomfield, Ne 67818

Facility ID:

2377

Facility Location:

Stingers One Stop

202 E Main, St

Bloomfield, Ne 68718

Dear Mr. Gill,

Due to failure to comply with the requirements of Title 159 Chapter 7, Chapter 5 and Chapter 13, tanks 07 and 08 of your facility are hereby subject to delivery prohibition. Title 159 specifies Underground Storage Tank (UST) systems may be subject to delivery prohibition as a result of non-compliance with Leak Detection Requirements of Chapter 7. (Title 159 001.01B) Overfill Requirements Chapter 5. (Title 159 Chapter 5 001.01D) Operator Training Requirements of Chapter 13. (Title 159 Chapter 13 001.01F) Lawful orders were issued to correct the above items on December 16, 2024, January 30, 2025 and March 28, 2025, during which time none of these items have been resolved.

The following list applies to UST systems subject to delivery prohibition:

- A. No owner or operator may deposit or accept the deposit of any regulated substance into an UST system that has been designated as ineligible for fuel deliveries by the application of a red tag. TITLE 159 11-002.01
- B. No product deliverer or other person may deliver or deposit any regulated substance into an UST system that has been designated as ineligible for fuel deliveries by the application of a red tag. TITLE 159 11-002.02
- C. No person other than the State Fire Marshal shall remove a red tag from an UST system without prior approval. TITLE 159 11-003.01

D. The State Fire Marshal shall verify compliance within two (2) business days of receiving a communication from the owner or operator that the corrections have been made. If the UST system is found to be eligible for delivery, the State Fire Marshal shall remove the red tag. As soon as practicable, but no more than three (3) business days after removal of the red tag, the facility shall be removed from the State Fire Marshal website list of sites ineligible for delivery. TITLE 159 11-003.02

In order to resume receiving fuel deliveries, please correct the violations as outlined on the attached order form and associated comments sheet. We look forward to resolving these items with you as quickly as possible.

Sincerely,

Larry Wiese #8742

Larry Wiel

Deputy State Fire Marshal Fuels Division, FLST Section

Office (402) 471-9465



## Nebraska State Fire Marshal

### **General UST Facility Comments/Corrections**

246 South 14<sup>th</sup> Street Lincoln, NE 68508 (402) 471-9465

Facility Name:	Date:	Fac ID#	
STINGERS ONE STOP	05/01/2025	2377	
Facility Address:		Number of USTs:	
202 E MAIN ST, BLOOMFIELD	2		

#### **Comments/Corrections Required**

#### Revisit Inspection #3

The following violations at this facility shall be corrected within 90 Days of this inspection:

- 1. Dispenser 1/2. Breakaways and swivels need to be replaced due to surpassing manufactures "remove by date".
- 2. Dispenser 1. Nozzle needs to be replaced due to surpassing manufactures "remove by date".
- 3. Dispenser 2. Long hose needs to be replaced due to damage.
- 4. Dispenser 1/2. There is evidence of a fuel leak from the upper portion of dispenser 2. Dispenser to remain out of use until repaired.
- 5. Dispenser 3/4. Both hose are required to swivel installed.
- 6. Dispenser 3. Replace long hose due to damage.
- 7. Dispenser 3. Nozzle needs to be replaced due to surpassing manufactures "remove by date".
- 8. No inventory available. Daily Inventory shall be made available upon inspection.
- 9. No ATG annual inspection. All three annual Automatic Tank Gauge inspections shall be made available upon inspection.
- 10. Facility needs spill buckets tightness tested. Last three test results are to be on site for three years.
- 11. Facility needs to provide a current and or up to date overfill protection test. Last 3 test results are to be on site for three years.
- 12. Facility is required to do monthly and annual walkthrough inspections on spill prevention and release detection equipment. Monthly walkthrough and annual walkthrough inspection shall be kept at the facility for a 3 year time period.

Inspector's Signature:  LARRY WIESE 8742	<b>Date:</b> 05/01/2025	
Owner/Operator Name: Jeremy Gill	Date:	
Signature:	05/01/2025	



# Nebraska State Fire Marshal FLST Section

## **General UST Facility Comments/Corrections**

246 South 14<sup>th</sup> Street Lincoln, NE 68508 (402) 471-9465

Facility Name:	Date:	Fac ID#
STINGERS ONE STOP	05/01/2025	2377
Facility Address:	Number of	f USTs:
202 E MAIN ST, BLOOMFIELD	2	

#### **Comments/Corrections Required**

#### Revisit Inspection #3

The following violations at this facility shall be corrected within 90 Days of this inspection:

- 14. Facility is required to have current and up to date records that are to be made available for inspection to become and or remain in compliance. ALL records need to be in a single location.
- 15. SFM reports on December 16<sup>th</sup>, 2024, January 30th, 2025, March 28th, 2025 and today's report state that the listed line item violation have not been corrected, this facility is not in compliance for approval. Due to uncorrected violations this facility will be in "Red-Tagged Prohibition" prohibiting delivery to tank(s) 07 & 08. This is in accordance with TITLE 159 CH 11, 001.01.
- 16. Within the next 90 days of this inspection, this facility shall have the listed violations corrected. Uncorrected violations will remain in "Red-Tagged Prohibition" status prohibiting delivery to tank(s) 07 & 08. This is in accordance with TITLE 159 CH 11, 001.01.
- **001.01** Any UST system may be subject to delivery prohibition procedures when a facility is determined to be out of compliance with any of following provisions of Title 159:
- 001.01A. Tank registration requirements of Chapter 2;
- 001.01B. Leak detection requirements of Chapter 7;
- 001.01C. Spill prevention requirements of Chapter 5;
- 001.01D. Overfill requirements of Chapter 5;
- 001.01E. Record keeping requirements of Chapters 5, 6, 7; Corrosion protection requirements of Chapter 4; or
- 001.01F. Failure to designate a Class A, Class B and/or Class C operators pursuant to Chapter 13.

Inspector's Signature:

LARRY WIESE 8742

Os/01/2025

Owner/Operator Name:

Jeremy Gill

Signature:

05/01/2025



## Nebraska State Fire Marshal FLST Section

## **General UST Facility Comments/Corrections**

246 South 14<sup>th</sup> Street Lincoln, NE 68508 (402) 471-9465

Facility Name: STINGERS ONE STOP	<b>Date:</b> 05/01/2025	2377
Facility Address:	Number o	f USTs:
202 E MAIN ST, BLOOMFIELD	2	

### **Comments/Corrections Required**

#### Revisit Inspection #3

The following violations at this facility shall be corrected within 90 Days of this inspection:

- 17. See Orders page for further explanation of "Red-Tagged Prohibition" TITLE 159 CH 11, 001.01.
- 18. Tank 7, E10, ATG states 448 gallons remaining, red- tag #0002456, stick measurement 12".
- 19. Tank 8, unleaded, ATG states 3165 gallons remaining, red-tag #0002457, stick measurement 38".
- 20. Do not remove red tag from any tank fill pipe until ALL ITEMS ARE completed. Facility will be revisited periodically.
- 21. If work is to be done, DSFM Wiese is the only authorized person to remove red-tags, unless otherwise directed by Chief Levering to authorize replacement personnel.

Inspector's Signature:	Date:
LARRY WIESE 8742	05/01/2025
Owner/Operator Name:	Date:
Jeremy Gill	
Signature: Ally Sill	05/01/2025