

State of Nebraska Underground Storage Tank Summary Information

Report Period: October 1, 2023, to September 30, 2024

This report has been prepared pursuant to EPA's Public Record UST Grant Guidelines.

Questions about the General Information and On-Site Inspections may be addressed to the State Fire Marshal's Office at 402-471-9465. Questions about Confirmed Releases may be addressed to the Department of Environment and Energy Petroleum Remediation Section at 402-471-2186. For a list of "Leaking UST and Surface Spill Sites" see NDEE's website at http://dee.ne.gov under Programs/Petroleum Remediation/ LUST & Surface Spill Site Information.

Date Posted: 1/28/2025

General Information

Total Number of UST Facilities: 2,202
Total Number of USTs: 6,346

On Site Inspections

UST Facilities Inspected: 680

Percentage of Facilities Inspected Found To Be In Compliance <u>51%</u> (With Release Detection <u>and</u> Release Prevention Regulations)

Releases

of Confirmed UST Releases: 58

Leak Autopsy Report

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	16	28%	1	33%	11	100%	0	0%	4	67%	0	0%	0	0%	0	0%
Piping	6	10%	1	34%	0	0%	4	16%	1	17%	0	0%	0	0%	0	0%
Dispenser	22	38%	1	33%	0	0%	19	76%	1	16%	1	100%	0	0%	0	0%
Submersible Turbine Pump	2	3%	0	0%	0	0%	2	8%	0	0%	0	0%	0	0%	0	0%
Other (e.g. unknown)	12	21%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	12	100%
Totals	58	100%	3	100%	11	100%	25	100%	6	100%	1	100%	0	100%	12	100%