



State of Nebraska Underground Storage Tank Summary Information

Report Period: October 1, 2024, to September 30, 2025

This report has been prepared pursuant to EPA's Public Record UST Grant Guidelines.

Questions about the General Information and On-Site Inspections may be addressed to the State Fire Marshal's Office at 402-471-9465. Questions about Confirmed Releases may be addressed to the Department of Environment and Energy Petroleum Remediation Section at 402-471-2186. For a list of "Leaking UST and Surface Spill Sites" see NDEE's website at <http://dee.ne.gov> under Programs/Petroleum Remediation/ LUST & Surface Spill Site Information.

Date Posted: 11/19/2025

General Information

Total Number of UST Facilities: **2,123**
Total Number of USTs: **6,227**

On Site Inspections

UST Facilities Inspected: **715**

Percentage of Facilities Inspected Found To Be In Compliance **69%**
(With Release Detection *and* Release Prevention Regulations)

Releases

of Confirmed UST Releases: **59**

Leak Autopsy Report

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	5	8%	0	0%	5	50%	0	0%	0	0%	0	0%	0	0%	0	0%
Piping	12	20%		0%	0	0%	9	90%	3	75%		0%		0%		0%
Dispenser	14	24%	8	80%	5	50%	1	10%	0	0%		0%		0%		0%
Submersible Turbine Pump	3	5%	2	20%	0	0%	0	8%	1	25%	0	0%	0	0%	0	0%
Other (e.g. unknown)	25	43%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	25	100%
Totals	59	100%	10	100%	10	100%	10	100%	4	100%	0	100%	0	100%	25	100%