



# State of Nebraska

## Underground Storage Tank Summary Information

Report Period: October 1, 2022, to September 30, 2023

*This report has been prepared pursuant to EPA's Public Record UST Grant Guidelines.*

Questions about the General Information and On-Site Inspections may be addressed to the State Fire Marshal's Office at 402-471-9465. Questions about Confirmed Releases may be addressed to the Department of Environment and Energy Petroleum Remediation Section at 402-471-2186. For a list of "Leaking UST and Surface Spill Sites" see NDEE's website at <http://dee.ne.gov> under Programs/Petroleum Remediation/ LUST & Surface Spill Site Information.

**Date Posted: 11/03/2023**

### General Information

Total Number of UST Facilities: **2,147**  
Total Number of USTs: **6,231**

### On Site Inspections

# UST Facilities Inspected: **835**

Percentage of Facilities Inspected Found To Be In Compliance **46%**  
(With Release Detection *and* Release Prevention Regulations)

### Releases

# of Confirmed UST Releases: **55**

### Leak Autopsy Report

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	16	29%	0	0%	2	100%	0	0%	2	67%	0	0%	0	0%	12	71%
Piping	7	13%	0	0%	0	0%	1	4%	1	33%	1	100%	0	0%	4	24%
Dispenser	26	47%	3	100%	4	0%	19	76%	0	0%	0	0%	0	0%	0	0%
Submersible Turbine Pump	5	9%	0	0%	0	0%	5	20%	0	0%	0	0%	0	0%	0	0%
Other (e.g. unknown)	1	2%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	1	5%
Totals	55	100%	3	100%	6	100%	25	100%	3	100%	1	100%	0	100%	17	100%