



State of Nebraska

Underground Storage Tank Summary Information

Report Period: October 1, 2013 to September 30, 2014

This report has been prepared pursuant to EPA's Public Record UST Grant Guidelines.

Questions about the General Information and On-Site Inspections may be addressed to the State Fire Marshal's Office at 402-471-9465. Questions about Confirmed Releases may be addressed to the Department of Environmental Quality Petroleum Remediation Section at 402-471-2186. For a list of "Leaking UST and Surface Spill Sites" see NDEQ's website at www.deq.state.ne.us under Programs/Petroleum Remediation/LUST & Surface Spill Site Information.

Date Posted: January 28, 2015

General Information

Total Number of UST Facilities: **2377**
 Total Number of USTs: **6629**

On Site Inspections

UST Facilities Inspected: **726**

Percentage of Facilities Inspected Found To Be In Compliance **59%**
(With Release Detection and Release Prevention Regulations)

Releases

of Confirmed UST Releases: 65

Leak Autopsy Report

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	
Tank	6	9%	0	0%	0	0%	2	12%	2	50%	0	0%	1	20%	1	4%
Piping	10	15%	0	0%	0	0%	4	25%	2	50%	0	0%	0	0%	4	14%
Dispenser	12	19%	0	0%	0	0%	10	63%	0	0%	1	100%	0	0%	1	4%
Submersible Turbine Pump	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%
Delivery Problem	10	15%	0	0%	9	90%	0	0%	0	0%	0	0%	1	20%	0	0%
Other (e.g. unknown)	27	42%	1	100%	1	10%	0	0%	0	0%	0	0%	3	60%	22	78%
Totals	65	100%	1	100%	10	100%	16	100%	4	100%	1	100%	5	100%	28	100%